Oil Field Environmental Incident Summary

Responsible Party: EOG RESOURCES, INC. **Well Operator:** EOG RESOURCES, INC.

Well Name: LUCILLE 22-06H

Field Name: PARSHALL Well File #: 18171

Date Incident:10/24/2016Time Incident:08:50Facility ID Number:County:MOUNTRAILTwp: 153Rng: 90Sec: 6Qtr:

Location Description:

Submitted By: Brenda Vaness Received By:

Contact Person: Brenda Vaness

600 17TH ST STE 1000N DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Stuffing Box Leak

Release Contained in Dike: Yes - On Facility Site Reported to NRC: No

Spilled Units Recovered Units Followup Units
Oil 2 Barrels 2 Barrels 2 barrels

Brine Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 1/4/2017 Clean Up Concluded: 10/24/2016

Risk Evaluation:

N/A

Areal Extent:

Potential Environmental Impacts:

N/A

Action Taken or Planned:

Standing liquids were removed with a vac truck, and contaminated material will be remediated on-site.

Wastes Disposal Location: Liquids to EOG SWD

Agencies Involved:

Updates

Date: 10/26/2016 Status: Reviewed - Assigned to Other Agency Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to stuffing box leak, remained on location within the diking according to the report. NDIC retains oversight.